Monitoring Data Record

Project Title: R-2568B (Site 4)	COF Action ID:	200121280					
Stream Name: UT to Rich Fork Creek							
City, County and other Location Information							
to North of SR 1756 (Lexington Ave.) Sta.		107 110111 (01111 01 1 00 2 00 1110 01					
Date Construction Completed: water was tu		nted on 2/17/06					
Monitoring Year: (5) of 5							
Ecoregion:	8 digit HUC unit_	03040103					
USGS Quad Name and Coordinates:							
Rosgen Classification:							
Length of Project: 315' Urban or Ru	ıral: Rural W	atershed Size:					
Monitoring DATA collected by: M. Green							
Applicant Information:							
Name: NCDOT Roadside Environn	nental Unit						
Address: 1425 Rock Quarry Road)					
Telephone Number: (919) 861-3772	_	dress: mlgreen@ncdot.gov_					
Consultant Information:							
Name:							
Address:							
Telephone Number:	Telephone Number: Email address:						
Project Status: Complete							
Monitoring Level required by COE and I Monitoring Level 1 requires completion of Permit States: NCDOT shall perform the each year for the 5 year monitoring persurvival, and visual inspection of channels the first 5 years, NCDOT shall continudocumented. The bankfull events must occur the required bankfull events do not occur consultation with resource agencies, may describe the process of the p	of Section 1, Section 2 and e following componed iod (summer and watability. If less than ue monitoring until our during separate manduring the 5 year modern.	ents of Level I monitoring twice vinter): Reference photos, plant two bankfull events occur during I the second bankfull event is nonitoring years. In the event that ponitoring period, the USACE, in					
Section 1. <u>PHOTO REFERENCE SITES</u> (Monitoring at all levels must complete this section	n)						
Total number of reference photo location Dates reference photos have been taken a 8/15/08, 1/15/09, 8/10/09, 3/1/10, 6/17/10							
Individual from whom additional photos	can be obtained (na	ame, address, phone):					
Other Information relative to site photo refewith this report.							
If required to complete Level 3 monitor	ring only stop here: c	otherwise, complete section 2.					

	PLANT SURVIVAL an sheet indicating reference photos.
Identi	specific problem areas (missing, stressed, damaged or dead plantings):
Estim	ed causes, and proposed/required remedial action:
	IONAL COMMENTS, No. 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	IONAL COMMENTS: <u>Planted hardwood vegetation noted onsite includes</u> : <u>black willow and silky</u> live stakes. Other vegetation noted onsite includes: goldenrod, sedge, <i>Scripus</i> sp., sycamore,
tulip p	ar, woolgrass, red maple, sweetgum jewelweed, cattail, lespedeza, mimosa, Juncus sp., and various
	The streambank and floodplain were live staked with black willow and silky dogwood species. NCDC
propos	to discontinue plant survival monitoring at the UT to Rich Fork Creek stream relocation.

If required to complete Level 1 and Level 2 monitoring <u>only</u> stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. <u>Physical measurements of channel stability/morphology will not be required.</u> Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The channel is stable throughout the entire onsite stream relocation for the Year 5 Summer evaluation. There have been a total of five bankfull events visually documented during the five year monitoring period. These bankfull events were documented on the following dates: 7/18/06, 2/28/07, 1/23/08, 1/15/09, and 3/1/10. NCDOT proposes to discontinue channel stability monitoring at the UT to Rich Fork Creek stream relocation.

Date	Station	Station	Station	Station	Station
Inspected	Number	Number	Number	Number	Number
Structure					
Type					
Is water					
piping					
through or					
around					
structure?					
Head cut or					
down cut					
present?					
Bank or scour					
erosion					
present?					

Section 4. <u>DEBIT LEDGER</u>

The entire UT Rich Fork Creek stream mitigation site was used for the R-2568B project to compensate for unavoidable stream impacts.

UT Rich Fork Creek



PP #1 (Upstream)



PP #1 (Downstream)



PP #2 (Upstream)



PP #2 (Downstream)



PP #3 (Upstream) Year 5 Summer – June 2010



PP #3 (Downstream)

UT Rich Fork Creek



PP #4 (Upstream)



PP #4 (Downstream)

Year 5 Summer – June 2010

